

How to: Check Network Card in Windows ME

Summary

During troubleshooting your Lindsey Communications High Speed internet connection there are times that you will need to verify your Ethernet Network card is functioning correctly. Please follow the below steps to verify your Ethernet NIC is working correctly.

▶ Interactive Solution

▶ Manual Solution

1. Click **Start**, select **Settings** and click **Control Panel**.
2. Double-click the **System icon**.
3. Click the **Device Manager** tab.
4. Double-click **Network Adapters**.
5. Highlight the **Ethernet Adapter** and click **Properties**.
6. The Device status should say "This device is working properly."
 - If Device status says something different, then the message given should identify the problem the network card is having.
7. Click **OK**.

All Steps Complete.